

TACS-M™ QUICK REFERENCE GUIDE



POWER KNOB/DISPLAY BRIGHTNESS

Rotate clockwise to power ON and increase brightness. Rotate counter clockwise to decrease brightness and power OFF the unit.

POLARITY

Push power knob to toggle between Black Hot and White Hot.

CALIBRATION

Push and hold power knob for 3 seconds to activate calibration while the lens cover is closed.



MODE SELECT (BOTH BUTTONS FUNCTION THE SAME)

Press to cycle between Full Thermal (High Thermal Sensitivity), Patrol (Reduced Thermal Sensitivity), and Outline (Outlines Hot or Cold objects).

USER MENU

Push and hold mode select button for 5 seconds to enter menu system. Push mode select to advance to next item. Push the power knob to select/change item.



ITEM	OPTION(S)
EXIT	(SURE?)
RESET	(SURE?)
COMPASS	(N/A, OFF, DEG-MOM, DEG-CON, MIL-MOM, MIL-CON, FUL-CAL, QCK-CAL)
MAGVAR	(+000.0)
FLIPDLY	(OFF, 15s, 30s, 1m, 2m)
SENS	(1, 2, 3, 4, 5)
PULSING	(OFF, BOTH, OUTLINE)
DEPTH	(10%, 20%, ..., 100%)
RATE	(1s, 2s, 4s, 6s, 8s)
ABC	(OFF, ON)
GAIN	(-8, ..., -1, AUTO, +1, ..., +8)
OFFSET	(-8, ..., -1, AUTO, +1, ..., +8)
ROT180°	(SURE?)

TACS-M™ QUICK REFERENCE GUIDE

