


TACS™ QUICK REFERENCE GUIDE



TACS™ QUICK REFERENCE GUIDE

OFF/ON/BRIGHTNESS:

- Detent between OFF/ON
- Rotate clockwise to turn on and increase brightness



Mode Select: (Press to cycle)

- Full Thermal (High Thermal Sensitivity)
- Patrol (Reduced Thermal Sensitivity)
- Outline (Outlines Hot or Cold Objects)

Polarity: (Press to toggle)

- Black Hot
- White Hot

Calibration: (Single-Point Image Correction)

- Push OFF/ON/BRIGHTNESS switch/button and hold for 3 seconds.